



DEPARTMENT OF THE NAVY

NORTHERN DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
10 INDUSTRIAL HIGHWAY
MAIL STOP, #82
LESTER, PA 19113-2090

03.01.00.0024

IN REPLY REFER TO

5090
Ser 1830/1821/JLC

Mr. John Molloy
H2M, Inc.
575 Broad Hollow Road
Melville, NY 11747

RE: BETHPAGE WATER DISTRICT WELL INFORMATION

Dear Mr. Molloy:

As discussed during the TRC meeting of March 10, 1993, the Navy is conducting computer modeling of the groundwater in the vicinity of the NWIRP Bethpage. To aid in this modeling effort, the Navy is requesting information from the Bethpage Water District on the potable water supply wells in the area. The specific information requested is as follows:

- * Current and historic well pumping rates (annual average, maximum monthly, and pump capacity) for each well near the NWIRP Bethpage.
- * Current and historic well depths, screen intervals, locations, and any aquifer testing conducted during well installation.
- * Summaries or trends of groundwater analytical data over the 5 years as well as any historic information which may be of interest. This information should focus on volatile organic compounds. However, if other parameters such as nitrates have been identified as a problem, this information is also requested.

Since this information is critical to our modeling efforts, we are requesting this information as soon as possible. If the information can be summarized on a limited number of sheets, please fax the information to Mr. James Colter, Code 1821, at (215) 595-0555. If the information is more extensive, please ship it directly to our consultants at Halliburton NUS as follows:


Mr. David Brayack
Halliburton NUS Corporation
Foster Plaza 7
661 Andersen Drive
Pittsburgh, PA 15220



RE: BETHPAGE WATER DISTRICT WELL INFORMATION

I would like to thank you for your continued cooperation and assistance in the Navy's remediation efforts at NWIRP Bethpage. If you have any questions regarding the above requested information, please call Mr. James Colter at (215) 595-0567.

Sincerely,

A handwritten signature in black ink, appearing to read 'TH G. SHECKELS', with a stylized, wavy line extending from the end.

THOMAS G. SHECKELS

Head, Restoration Management Section
By Direction of the Commanding Officer

Copy to:
DPRO, Marty Simonson
HNUS, David Brayack
NAVAIRSYSCOM, Bob Booth